## DESCO TECHNICAL BULLETIN TB-3073 =

## Multi-Mount Monitor Installation, Operation and Maintenance





Figure 1. Desco Multi-Mount Monitor

### Description

The Desco Multi-Mount Monitor is a single workstation continuous monitor. It continuously monitors the path-to-ground integrity of one operator and one ESD worksurface. Mounting tabs make it suitable to install in workbench or equipment settings. Connect the <u>19653</u> Remote Alarm accessory to the Multi-Mount Monitor, and place it in the operator's field of view for increased alarm visibility.

The Multi-Mount Monitor is designed with Wave Distortion Technology which provides stable continuous monitoring of the path-to-ground and presence of 1 megohm resistance of an operator's wrist strap. Audio and visual alarms activate (in less than 50 milliseconds) when the operator unintentionally disconnects from the monitor or the wrist strap connection points are intermittent. The Multi-Mount Monitor also monitors for a worksurface path-to-ground of less than 10 megohms. All Multi-Mount Monitors are calibrated to NIST standards and include a certificate.

## **WAVE DISTORTION**

Wave Distortion Technology is the Most Reliable Technology for the Continuous Monitoring of Single-Wire (Conductor) Wrist Straps "Wave Distortion" or vector impedance works by applying a continuous test voltage of 1.2 volts peak-to-peak at 1 to 2 microamperes (0.000002 amperes) to the wrist strap that is connected to the continuous or constant monitor. The test voltage creates a sine wave that the monitor circuit compares to established patterns. By monitoring the "distortions", or shape of the sine wave, Wave Distortion Technology determines if the monitored circuit is complete - the operator is in the circuit and the total equivalent DC resistance is within specifications. Wave Distortion Technology produces a very fast alarm time (<50 milliseconds) and minimal false alarms.

ANSI/ESD S20.20 section 7.3 states "Compliance verification records shall be established and maintained to provide evidence of conformity to the technical requirements." Per ANSI/ESD S1.1 Annex A.3 Daily (wrist strap system) testing may be omitted if constant monitoring used." Per ESD Handbook ESD TR 20.20 section 5.3.2.4.4 "Typical Test programs recommend that wrist straps that are used daily should be tested daily. However, if the products that are being produced are of such value that knowledge of a continuous, reliable ground is needed, and then continuous monitoring should be considered or even required."

The Multi-Mount Monitor and its accessories are available as the following item numbers:

ltem	Description	
<u>19651</u>	Multi-Mount Monitor, North American Power Adapter	
<u>19652</u>	Multi-Mount Monitor, Universal Power Adapter	
<u>19653</u>	Power Adapter, 100-240VAC Input, 24VDC 150mA Output, IEC Inlet	
<u>19258</u>		
<u>19260</u>		
<u>98220</u>	Calibration Unit for Wave Distortion Monitors	

### Packaging

### 19651 Multi-Mount Monitor, North America

- 1 Multi-Mount Monitor
- 1 Mat Monitor Cord (White)
- 1 Push and Clinch Snap
- 1 Countersunk Washer
- 1 Flat Head Screw, 6-32 x 1/4"
- 2 Pan-Head Screws, #6 x 3/8"
- 1 Dual Lock Fastener Set, 2" Length
- 1 Power Adapter, 24VDC, North America Plug
- 1 Certificate of Calibration



Figure 2. North American power adapter included with the 19651 Multi-Mount Monitor

### 19652 Multi-Mount Monitor, Universal Power Adapter

- 1 Multi-Mount Monitor
- 1 Mat Monitor Cord (White)
- 1 Push and Clinch Snap
- 1 Countersunk Washer
- 1 Flat Head Screw, 6-32 x 1/4"
- 2 Pan-Head Screws, #6 x 3/8"
- 1 Dual Lock Fastener Set, 2" Length
- 1 10mm Interchangeable Park Snap
- 1 Power Adapter, 24VDC, IEC Inlet
- 1 Certificate of Calibration



Figure 3. Universal power adapter included with the 19652 Multi-Mount Monitor

NOTE: The power cord must be purchased separately if ordering the 19652 Multi-Mount Monitor. The power cords are available as the following item numbers:

Item	Plug Type	
<u>50545</u>	Europe	
<u>50546</u>	United Kingdom	

### 19653 Remote Alarm

- 1 Remote Alarm
- 1 Remote Cable, 7' Length
- 2 Pan-Head Screws, #6 x 3/8"
- 1 Dual Lock Fastener Set, 1" Length



Figure 4. Desco <u>19653</u> Remote Alarm

## Features and Components

Multi-Mount Monitor



Figure 5. Multi-Mount Monitor features and components

**A. Mat Monitor Switch:** Use a probe to access the mini slide switch. Slide the switch to the right to enable the mat monitor circuit. Slide the switch to the left to disable the mat monitor circuit. This switch is enabled as default.

**B. Buzzer Volume Adjustment:** Turn the trimpot clockwise to increase the buzzer volume. Turn the trimpot counter-clockwise to decrease the buzzer volume.

**C. Monitored Operator Jack:** Insert the single-wire wrist cord here to monitor the operator's connection to ground.

**D. Operator LEDs:** Illuminates green when the operator is properly grounded. Illuminates solid red and audible alarm sounds when the operator is not properly grounded.

**E. Mat LEDs:** Illuminates green when the worksurface is properly grounded. Illuminates red and audible alarm sounds when the worksurface is not properly grounded.

**F. Park Snap:** Allows the operator to disconnect (and park) a wrist strap when leaving the workstation, without creating a false alarm. Touch the park snap and the monitor's audible alarm will disable for 6 seconds. Use this time to disconnect the wrist cord from the wristband, and attach it to the park snap or remove the banana plug from the jack. Upon returning to the workstation and disconnecting the wrist cord from the park snap, the operator has 6 seconds to reconnect the wrist cord to a worn wristband before activating the alarm.

**G. Mat Monitor Screw Terminal:** Verifies that the worksurface's path-to-ground is <10 megohms. Connect the white mat monitor cord here.

**H. Power Jack:** Connect the included 24VDC power adapter here.

**I. Remote Alarm Jack:** Connects to the <u>19653</u> Remote Alarm accessory.




Figure 6. Remote Alarm features and components

**A. Operator LEDs:** Illuminates green when the operator is properly grounded. Illuminates solid red and audible alarm sounds when the operator is not properly grounded.

**B. Mat LEDs:** Illuminates green when the worksurface is properly grounded. Illuminates red and audible alarm sounds when the worksurface is not properly grounded.

**C. Multi-Mount Monitor Jack:** Connects to the Multi-Mount Monitor.



*Figure 7. Installing the Multi-Mount Monitor and Remote Alarm accessory* 

- 1. Remove the Multi-Mount Monitor from the carton, and inspect for damage.
- Locate an appropriate AC outlet near the Multi-Mount Monitor, and test it for proper wiring and grounding prior to use. The Desco AC Outlet Analyzer or similar test equipment may be used to verify the outlet's functionality. Use item number <u>98132</u> for 120VAC North American outlets and item number <u>98131</u> for 220VAC UK outlets.
- Determine the mounting location of the Multi-Mount Monitor. Its LEDs should be visible to the operator. Secure the Multi-Mount Monitor to a surface using its mounting tabs and the included pan-head screws or dual lock fasteners.
- Secure the ring termination of the white mat monitor cord to the mat monitor screw terminal on the side of the Multi-Mount Monitor. Ensure that the mat monitor switch is enabled if using this monitored circuit.

5. Route the mat monitor cord from the side of the Multi-Mount Monitor to the worksurface mat.

NOTE: Use either the included push and clinch snap or countersunk washer and flat head screw to secure the cord to the grounded mat.

 Connect the power adapter to the power jack located on the side of the Multi-Mount Monitor. Route the wire from the supply to the tested AC outlet, and plug it into the outlet.

#### **Remote Alarm**

- Determine the mounting location of the optional <u>19653</u> Remote Alarm. Locate it within reach of the included remote cable. Its LEDs should be visible to the operator. Secure the Remote Alarm to a surface using its mounting tabs and the included pan-head screws or dual lock fasteners.
- 2. Connect the Remote Alarm to the Multi-Mount Monitor using the remote cable.






Figure 8. Mounting hole locations on the Multi-Mount Monitor (all dimensions are in inches)





#### 10mm Park Snap


The <u>19652</u> Multi-Mount Monitor includes an interchangeable 10mm park snap for operators who use wrist cords with a 10mm termination. Use the park snaps' knurled rims to unscrew the 4mm park snap from the monitor and install the 10mm park snap to the monitor.



*Figure 10.* Changing the park snap on the <u>19652</u> Multi-Mount Monitor

### Operation

- 1. Fit the wristband snugly onto the wrist.
- 2. Snap the wrist cord to the wristband.
- 3. Plug the wrist cord into the operator jack. The green operator LED will illuminate. This indicates that the operator is properly grounded.
- 4. If this does not happen, examine the wrist cord for continuity or damage and the wristband to ensure that it fits securely. If you have dry skin, apply an approved dissipative hand lotion such as <u>Menda</u> <u>Reztore® ESD Hand Lotion</u>.
- 5. When leaving the workstation, first touch the monitor's park snap. The monitor's audible alarm will disable for 6 seconds. Use this time to disconnect the wrist cord from the wristband and attach it to the park snap without sounding a false alarm.
- 6. Upon returning to the workstation and disconnecting the wrist cord from the park snap, the monitor will provide 6 seconds for the operator to reconnect the wrist cord to a worn wristband before sounding the monitor's alarm.



*Figure 11. Using the Multi-Mount Monitor and Remote Alarm in a workbench setting* 



Figure 12. Using the Multi-Mount Monitor at a machine station

## Calibration

Frequency of recalibration should be based on the critical nature of those ESD sensitive items handled and the risk of failure for the ESD protective equipment and materials. In general, Desco recommends that calibration be performed annually.

Use the Desco <u>98220</u> Calibration Unit for Wave Distortion Monitors to perform periodic verification (once every 6-12 months) of the Multi-Mount Monitor. The Calibration Unit can be used to check the test limits of the Multi-Mount Monitor without removing it from the workstation.

See TB-2082 for more information.



Figure 13. Desco <u>98220</u> Calibration Unit for Wave Distortion Monitors

## **Specifications**

85°F (30°Č)Dimensions (Monitor)3.87" L x 2.09" W x .90" H (98 mm x 53 mm x 23 mm)Dimensions (Remote Alarm)1.78" L x 1.08" W x .79" H (45 mm x 27 mm x 20 mm)Weight (Monitor)0.14 lbs. (0.06 kg) (Monitor)Weight (Remote Alarm)0.02 lbs. (0.01 kg) (Remote Alarm)Operator Test Range* impedance500 kilohms to 10 megohms impedanceWorksurface Test Limit**0perator Test Voltage1.2V peak-to-peak @ 1.2µA open circuit		-	
24VDC @ 150mA Cable Length: 5 ft. (1.5 m)Operating Temperature50 to 95°F (10 to 35°C)Environmental RequirementsIndoor use only at altitudes less than 6500 ft. (2 km) Maximum relative humidity of 80% up to 85°F (30°C) decreasing linearly to 50% decreasing linearly to 50% dec		Frequency	Power Input:
5 ft. (1.5 m)Operating Temperature50 to 95°F (10 to 35°C)Environmental RequirementsIndoor use only at altitudes less than 6500 ft. (2 km) Maximum relative humidity of 80% up to 85°F (30°C) decreasing linearly to 50% (85°F (30°C)) decreasing linearly to 50% (85°F (30°C))Dimensions (Monitor)3.87" L x 2.09" W x .90" H (98 mm x 53 mm x 23 mm)Dimensions (Monitor)1.78" L x 1.08" W x .79" H (45 mm x 27 mm x 20 mm)Weight (Monitor)0.14 lbs. (0.06 kg) (Monitor)Weight (Remote Alarm)0.02 lbs. (0.01 kg)Operator Test Range* Limit**500 kilohms to 10 megohms impedanceVorksurface Test Limit**10 megohms (±10%)			
Environmental RequirementsIndoor use only at altitudes less than 6500 ft. (2 km) Maximum relative humidity of 80% up to 85°F (30°C) decreasing linearly to 50% (85°F (30°C))Dimensions (Monitor)3.87" L x 2.09" W x .90" H (98 mm x 53 mm x 23 mm)Dimensions (Monitor)1.78" L x 1.08" W x .79" H (45 mm x 27 mm x 20 mm)Weight (Monitor)0.14 lbs. (0.06 kg)Weight (Remote Alarm)0.02 lbs. (0.01 kg)Operator Test Range* Limit**500 kilohms to 10 megohms impedanceVorksurface Test Limit**10 megohms (±10%)Operator Test Voltage open circuit1.2V peak-to-peak @ 1.2µA open circuit			
Requirementsless than 6500 ft. (2 km) Maximum relative humidity of 80% up to 85°F (30°C) decreasing linearly to 50% ( 85°F (30°C)Dimensions3.87" L x 2.09" W x .90" H (98 mm x 53 mm x 23 mm)Dimensions1.78" L x 1.08" W x .79" H (45 mm x 27 mm x 20 mm)Dimensions0.14 lbs. (0.06 kg) (Monitor)Weight (Remote Alarm)0.02 lbs. (0.01 kg)Operator Test Range*500 kilohms to 10 megohms impedanceWorksurface Test Limit**10 megohms (±10%)Operator Test Voltage1.2V peak-to-peak @ 1.2µA open circuit		Operating Temperature	50 to 95°F (10 to 35°C)
of 80% up to 85°F (30°C) decreasing linearly to 50% ( 85°F (30°C) Dimensions (Monitor) Dimensions (Remote Alarm) Weight (Monitor) Weight (Monitor) Unerstor Test Range* Operator Test Range* Operator Test Voltage Operator Test Voltage Operator Test Voltage Operator Test Voltage			
(Monitor)(98 mm x 53 mm x 23 mm)Dimensions1.78" L x 1.08" W x .79" H(Remote Alarm)(45 mm x 27 mm x 20 mm)Weight (Monitor)0.14 lbs. (0.06 kg)Weight (Remote Alarm)0.02 lbs. (0.01 kg)Operator Test Range*500 kilohms to 10 megohms impedanceWorksurface Test Limit**10 megohms (±10%)Operator Test Voltage1.2V peak-to-peak @ 1.2µA open circuit			of 80% up to 85°F (30°C) decreasing linearly to 50% @
(Remote Alarm)(45 mm x 27 mm x 20 mm)Weight (Monitor)0.14 lbs. (0.06 kg)Weight (Remote Alarm)0.02 lbs. (0.01 kg)Operator Test Range*500 kilohms to 10 megohms impedanceWorksurface Test Limit**10 megohms (±10%)Operator Test Voltage1.2V peak-to-peak @ 1.2µA open circuit		2	
(Monitor)0.02 lbs. (0.01 kg)Weight (Remote Alarm)0.02 lbs. (0.01 kg)Operator Test Range* impedance500 kilohms to 10 megohms impedanceWorksurface Test Limit**10 megohms (±10%)Operator Test Voltage open circuit1.2V peak-to-peak @ 1.2µA open circuit			
(Remote Alarm)Operator Test Range*500 kilohms to 10 megohms impedanceWorksurface Test Limit**10 megohms (±10%)Operator Test Voltage1.2V peak-to-peak @ 1.2µA open circuit			0.14 lbs. (0.06 kg)
impedance Worksurface Test Limit** Operator Test Voltage 1.2V peak-to-peak @ 1.2μA open circuit			0.02 lbs. (0.01 kg)
Limit** Operator Test Voltage 1.2V peak-to-peak @ 1.2µA open circuit		Operator Test Range*	500 kilohms to 10 megohms impedance
open circuit			10 megohms (±10%)
		Operator Test Voltage	1.2V peak-to-peak @ 1.2µA, open circuit
Vorksurface lest 5 to 7.5V, open circuit Voltage		Worksurface Test Voltage	5 to 7.5V, open circuit
Alarm Response Time <50 ms		Alarm Response Time	<50 ms
		Country of Origin	United States of America

\*This cannot be verified with standard DC test equipment. The continuous monitor is an impedance sensing device, and the limits are determined by the magnitude and angle of the impedance.

\*\*The worksurface mat must have a conductive layer such as Dual Layer Rubber or Dissipative 3-Layer Vinyl with conductive buried layers. Desco workstation monitors are not recommended for use with homogeneous matting.

# Limited Warranty, Warranty Exclusions, Limit of Liability and RMA Request Instructions

See the Desco Warranty http://desco.descoindustries.com/Limited-Warranty.aspx