


- Machine Tap
- Maschinen-Gewindebohrer
- Machinetappen
- Tarauds machine
- Machos de máquina
- Macho de Máquina



E207



- 1.3 1.4
- 1.2 1.5 7.2 7.3

M	P mm	l ₁ mm	l ₂ mm	d ₂ Ø mm	a mm	l ₃ mm	z	↔	l ₄ mm	e-Code
2	0.40	45	4	2.8	2.1	5	3	1.6	9	E207M2
2.5	0.45	50	4	2.8	2.1	5	3	2.05	12.5	E207M2.5
3	0.50	56	9	3.5	2.7	6	3	2.5	18	E207M3
3.5	0.60	56	11	4.0	3.0	6	3	2.9	20	E207M3.5
4	0.70	63	12	4.5	3.4	6	3	3.3	21	E207M4
5	0.80	70	13	6.0	4.9	8	3	4.2	25	E207M5
6	1.00	80	15	6.0	4.9	8	3	5	30	E207M6
7	1.00	80	15	7.0	5.5	8	3	6	30	E207M7
8	1.25	90	18	8.0	6.2	9	3	6.8	35	E207M8
10	1.50	100	20	10.0	8.0	11	3	8.5	39	E207M10