


Product Information

Purpose of this form is to document that our customers noticed shipments of **parts deviating from specified values**.

Part number: Y1 Modules like MCC, MCD, MDD 312, 255, 254, 175 and MCO, MDO 450, 500, 600			
Customer:	Company	Attn. Of	Fax:
<p>Deviations from standard (specification / technical deviations in detail, if necessary specify and attach additional documents, possible consequences for the application):</p> <p><i>Due to a sudden shut down of a sub-supplier molding company, our direct supplier is not able to ship the grooved pin any more. This is necessary to hold the lid on the device during transportation and storage.</i></p> <p><i>This grooved pin is a standard DIN part available in quantities on the market. Unfortunately, it can be purchased with reasonable lead times only in white color. The mold material is the same. The 'black version' is available at the earliest in 12 weeks.</i></p> <p><i>Even if IXYS works specially towards reducing the lead time, it becomes necessary to use grooved pins with white color for a period of maximal 12 weeks beginning with date code 1129 (2011, week 29).</i></p>			
			
Requested by:	Date	Name	Signature
	07/15/2011	Dr. Stippich Department Quality Management Phone +40 6206 503847	

distribution / file:

IXYS / Sales IXYS / Q Produktordner IXYS / TA 2